



Wrinkle Plus™ Coating

Product Description

VHT® Wrinkle Plus™ Coating combines strong colors with a deep rich texture for a custom look, it is temperature resistant to 350° F (177° C) and is ideal for adding a touch of personal styling to almost any metal surface. It resists color fading, grease, degreasers, and severe weather degreasers.

Product Characteristics

Colors: Black and Red

Finish: Flat

Properties

Product Weight: 6.38 lb/gal

Flash Point: Propellant < 0° F

Coating System

VHT provides a multi-high performance coating system for the ultimate in protection and quality. The system includes surface preparation, primer, and paint.

Prep SP445 Prep Spray

Prime SP148 Engine Primer

Coat SPxxx Wrinkle Plus Color

Uses

Valve Covers, Metal Dashboards, Glove Boxes, Starters, Door Panels, Shifters, Alternators, and Firewalls.

Surfaces:

- Metal & Plastic

Packaging

Fill Weight: 11.25 oz

Per Case: 6 cans

Case Weight: 5.82 lbs

Cases/Pallet: 156

Units/Pallet: 936

Application

Caution: For maximum product performance read entire label and directions prior to paint application.

Prepare surface by removing loose paint, dirt, rust, grease, wax, etc. For best results use grease and wax remover to clean surface. Scuff /sand surface with a Red Scotch Brite pad or equivalent until bare metal. Wipe surface down again with grease and wax remover.

Mask off surrounding areas to protect from overspray. Use at temperatures between 60° F (16° C) and 95° F (35° C).

Shake can vigorously for one full minute after mixing ball moves freely. Shake can for 10 seconds after each minute of use. To spray, hold can parallel 8 to 10 inches from surface being painted and use in an even, sweeping motion. Apply at least three heavy coats in a crosshatch pattern. First coat vertically, second coat horizontally, and third coat diagonally. Allow five minutes between each coat. A relatively heavy film thickness is required for the product to wrinkle.

This paint dries very slowly. A “wrinkle” finish does not appear immediately after spraying. Allow 2 hours to air dry. If paint fails to wrinkle or wrinkles in an uneven pattern, apply an additional coat of paint in unwrinkled areas. Although paint appears dry, avoid any contact with surface for at least 24 hours. Allow 48 hours or more before reassembling parts.

The EZ Touch™ Nozzle results in 50% less finger fatigue than a standard nozzle, as well as allowing greater coverage and less overspray.

Curing

VHT Wrinkle Plus only attains its unique properties after correct curing.

Off of Vehicle: Bake at 200° F (93° C) for 20 minutes.

On the Vehicle: The inherent heat of engine operation will also accomplish curing.

Note that this may cause the wrinkles to be tighter.